Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO0836Work Order Type: WeatherizationAudit Name: 14014SO0836

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO0836 LEWISBURG, TN 37034

Alt. Client ID: MARSHALL

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO0836
Alt. Client ID: MARSHALL

Work Order (Bid Form)
Work Order Name: 14014SO0836
Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 7

Measure 1 G	eneral Air Sealing			Componen	ts			Inspected
USIN OR L		S AND RE	TURN	- REGISTE	RS TO R	READ 1.	.0	
	PLACE MISSING INSULA	TION AND	BELL	BOARD AF	TER DU	CT		
AREA	LING FAL AROUND WHERE ADI A OF INFILTRATION 'S AND D/S SIDE DOOR	OITION ME	ETS 1	TRAILER AN	ID ANY (OTHER	R	
4. ٧٧/	3 AND D/3 SIDE DOOR			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail								
		,	Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
	(INDOM)			Componen	to			Inspected
Measure 2 W	_	NI EAST S		Componen	ts			Inspected
Measure 2 W	/INDOW LACE MIDDLE WINDOW C)N EAST S		•			Actual	Inspected
Measure 2 W	_	ON EAST S		Componen Estimated Unit Cost		Qty	Actual Unit Cost	
Measure 2 W Comment REPL	ACE MIDDLE WINDOW C		SIDE	Estimated		Qty		
Measure 2 W Comment REPL # Material / Labor	ACE MIDDLE WINDOW C Description / Comment REPLACEMENT	Units	Qty	Estimated		Qty		
Measure 2 W Comment REPL # Material / Labor 1 Windows	Description / Comment REPLACEMENT WINDOW	<i>Units</i> Each	Qty	Estimated		Qty		
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor	Description / Comment REPLACEMENT WINDOW	<i>Units</i> Each	Qty	Estimated		Qty		
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor	Description / Comment REPLACEMENT WINDOW	<i>Units</i> Each	Qty	Estimated		Qty		
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor	Description / Comment REPLACEMENT WINDOW	Units Each Hour	Qty 1	Estimated				
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor	Description / Comment REPLACEMENT WINDOW	Units Each Hour	Qty 1	Estimated Unit Cost			Unit Cost	
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor Other Detail	Description / Comment REPLACEMENT WINDOW	Units Each Hour	Qty 1	Estimated Unit Cost			Unit Cost	
Measure 2 W Comment REPL # Material / Labor 1 Windows 2 Labor Other Detail	Description / Comment REPLACEMENT WINDOW	Units Each Hour	Qty 1	Estimated Unit Cost			Unit Cost	

Client Name: Client ID: 14014SO0836 Alt. Client ID: MARSHALL

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: 14014SO0836 Report Run On: 5/14/2010

Measure 3 DO	ORS			Componei	nts			Inspected
Comment REPLA	ACE DOOR TO ADDITION							
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	REPLACEMENT DOOR	Each	1					
2 Labor	LABOR	Hour						
Other Detail			1		Г	, ,		
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								
	051.0400			0	-4-			Inonactad
	SELOADS			Componer	าเร			Inspected
	PLACE REFRIGERATOR			IDEC				
2. W R/	AP TANK / INSULATE HO	I AND C	OLD P	Estimate	4		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	REPLACEMENT	Each	1	Omit Oost	Total	Q.y		70107
1 Refrigerators	REFRIGERATOR	Lacii	'					
2 Labor	LABOR	Hour						
3 Hot Water Equipment	WRAP TANK	Each	1					
4 Labor	LABOR	Hour						
5 Hot Water Equipment	INSULATE LINES	Each	1					
6 Labor	LABOR	Hour						
Other Detail			1		Г	7		
			Measur	e Sub Total:]	Sub Total:	
Field Notes:								

Client Name: Client ID: 14014SO0836 Alt. Client ID: MARSHALL Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Work Order Name: 14014SO0836 Report Run On: 5/14/2010

	<i>Measure</i> 5 Fix II	mproper Venting (Cloth	nes Dryer)		Componen	ts			Inspected
C	omment CHANG	E TO METAL FLEX AND) INSTALL	. DAM	PER				
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Metal Flex	Each	1					
2	Labor	Labor	Hour	1					
C	ther Detail								
			ı	Measur	e Sub Total:] ;	Sub Total:	
	Field Notes:								

Measure 6	Fix Wiring Problems
	(Basement/Crawlspace)

Components

_			
ln.	200	~~+	_
1113	spe		ш

Comment 1. INSTALL 2 WALL RECEPTICALS IN LVROOM - REPAIR WALL AROUND ONE

2. REPLACE THERMOSTAT / SERVICE UNIT

				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety Items	WALL OUTLET	Each	2						
2	Labor	Labor	Hour	1						
3	Heating Equipment	REPLACEMENT THERMOSTAT	Each	1						
4	Labor	LABOR	Hour							
5	Heating Equipment	SERVICE UNIT	Each	1						
6	Labor	LABOR	Hour							
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									

Report Run On: 5/14/2010

its Qty	Estimated Unit Cost	<u> </u>			
	Unit Cost			Actual	
า 1		Total	Qty	Unit Cost	Total
r 1					
Meas	ure Sub Total:			Sub Total:	
	•			Actual	Inspected
				Actual	
ts Qtv	' Unit Cost	i otai	Qtv	Unit Cost	Total
its Qty n 1	Unit Cost	Total	Qty	Unit Cost	Total
	Unit Cost	I otal	Qty	Unit Cost	Total
n 1	Unit Cost	I otal	Qty	Unit Cost	Total
n 1	Unit Cost	Iotal	Qty	Unit Cost	Total
n 1	Unit Cost	Iotal		Unit Cost	Total
		Estimated	Components Estimated	Components	

Report Run On: 5/14/2010

Meas	sure 9	Vapor Barrier Needed (Basement/Crawlspace)			Componen	ts		ı	nspected
Comn	nent								
					Estimated	<u> </u>		Actual	
# Mate	erial / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insu	lation	Basement / crawlspace vapor barrier	Each	1					
2 Lab	or	Labor	Hour	1					
Other	Detail						-		
] []		
				Measur	e Sub Total:]	Sub Total:	
Field	Notes:						_		
			Work Or	der Gra	nd Total:		Gran	d Total:	<u> </u>